



GIUNTI CARDANICI A PERNI



Giunto	D	F _{H7}	L	P	Giunto	LD	M	B x C	Q/ES
semplice	mm	mm	mm	mm	doppio	mm	mm	mm	mm
G10P	10	5	28	8	GD10P	*	14	*	*
G13P	13	6	34	11	GD13P	57	17	2 x 7	6
G17P	17	8	40	12	GD17P	67	20	2 x 9	8
G20P	20	10	45	13	GD20P	75	22,5	3 x 11,4	10
G23P	23	12	50	14	GD23P	84	25	4 x 13,8	12
G26P	26	14	56	16	GD26P	92	28	5 x 16,3	14
G29P	29	16	65	18	GD29P	106	32,5	5 x 18,3	16
G32P	32	18	72	20	GD32P	119	36	6 x 20,8	18
G35P	35	20	82	24	GD35P	132	41	6 x 22,8	20
G40P	40	22	95	28	GD40P	151	47,5	6 x 24,8	22
G45P	45	25	108	34	GD45P	176	54	8 x 28,3	25
G50P	50	30	122	37	GD50P	194	61	10 x 33,3	28
G55P	55	35	140	42	GD55P	219	70	10 x 38,3	32
G60P	60	40	160	50	GD60P	248	80	12 x 43,3	36
G70P	70	45	175	50	GD70P	264	87,5	14 x 48,8	*
G80P	80	50	190	55	GD80P	286	95	14 x 53,8	*
G90P	90	55	210	65	GD90P	310	105	16 x 59,3	*
G100P	100	60	230	70	GD100P	360	115	18 x 64,4	*

